


SWR/Power/Return Loss monitor

Propeller program flow diagram

30 Apr 2009



Propeller flow chart showing the interaction of the cogs. The MAIN program runs in a cog of its own and starts three other cogs: ADC3CH, PWM and MONITOR. ADC3CH in turn starts a new cog, ADC; and MONITOR starts a new cog, PCMON.